



FAILURE ANALYSIS REPORT

**FA QEM-CCR-1709-00009
ACTION-0074312**

Analyst: Priority Labs

Reviewed: Scott Lisula Date: 9-9-17

Dallas

Device: TUSB4041IPAPRQ1

Priority Labs, Inc.

1001 S. Sherman St. Suite 600

Richardson, Texas 75081



Customer:	SERIAL SYSTEM (DSTR)	Assy Site:	PHI
Customer Tracking ID:		Fab Site:	DM6
Customer Part ID:		Technology:	C021
Customer Contact:	gujiabin	Analyst:	Scott Lisula
Device Type:	TUSB4041IPAPRQ1	TI Contact:	Lisa Liu(CQE SZ)
Flow Type:	Customer Return	Qty Submitted:	1
Reviewer:		Date Submitted:	2017-09-07
		Approval:	

SUMMARY

Fail Mode: One device was submitted for analysis.

Fail Mech: EOS damage was observed in the form of degraded mold compound, damaged, and reflowed metal. EOS damage was observed at the silicon layer.

Conclusion: The device failed due to an electrical overstress event.

TI Unit #	Cust. Unit #	Lot Trace Code	Symbolization	Wafer Fab Lot #	Assembly Lot #
1		73AF26W		6283871	7115513WCW

- **Customer Problem Description**

Customer: Coagent;
Failed step: NPI
failure description:
pin 33 and pin 34(USB1 D+/-) waveform anomaly;

- **TI Problem Description**

2017/09/01: 1pcs sample received

- **External Visual Inspection**

External visual inspection did not reveal any anomalies or defects.




Figure Number: 1
Unit Number: 1

Optical image of the top side external condition of the package.




Figure Number: 2
Unit Number: 1

Optical image of the bottom side external condition of the package.

- **X-ray Analysis**

X-ray analysis did not reveal any anomalies or defects. The bond wires were in place and no anomalous bond wire sweep was observed.




Figure Number: 3
Unit Number: 1

X-ray analysis did not reveal any anomalies.




Figure Number: 4
Unit Number: 1

High magnification X-ray analysis did not reveal any anomalies.




Figure Number: 5
Unit Number: 1

Angled X-ray analysis did not reveal any anomalies.




Figure Number: 6
Unit Number: 1

Side view X-ray analysis did not reveal any anomalies.

- **Scanning Acoustic Microscopy**

Scanning Acoustic Microscopy (SAM) did not reveal any delamination at the package/die interface.




Figure Number: 7
Unit Number: 1

SAM analysis did not reveal any delamination at the package/die interface.

- **Electrical Characterization**

An all pins curve trace confirmed the reported short from pin 33 and pin 34 to GND, when compared to a correlation unit.




Figure Number: 8
Unit Number: 1

Curve trace image showing a short from pin 33 to GND.




Figure Number: 9
Unit Number: 1

Curve trace image showing a short from pin 34 to GND.

- **Decapsulation and Internal Optical Inspection**

The device was decapsulated using wet chemical etchants. Optical inspection of the die circuitry revealed EOS damage in the form of degraded mold compound, damaged, and reflowed metal.




Figure Number: 10
Unit Number: 1
Layer: Protective Overcoat (PO)

Optical overview image showing the die area of the unit. EOS damage indicated by the red.




Figure Number: 11
Unit Number: 1
Layer: Protective Overcoat (PO)

High magnification optical image of the observed EOS damage, as indicated by the red.




Figure Number: 12
Unit Number: 1
Layer: Protective Overcoat (PO)

High magnification optical image of the observed EOS damage, as indicated by the red.




Figure Number: 13

Unit Number: 1

Layer: Protective Overcoat
(PO)

**High magnification optical
image of the observed EOS
damage, as indicated by the
red.**