
# TUSB2036 Troubleshooting

## Symptoms

- USB hub recognized
- Downstream devices show error "This device cannot start. (Code 10) Insufficient system resources exist to complete the API."
  - Flashdrive is recognized as "USB Mass Storage Device"
  - FTDI FT4232H only recognized as "USB Composite Device"
- No power complaints on my desktop
- On two laptops, windows gives two warnings for "The hub does not have enough power to support the [USB Mass Storage Device/USB Composite Device]"




#### Power-on Reset


- CH1 3.3V\_USB
- CH2 Reset
- CH3 XTAL1 pin
  - Due to 1MS/s rate the 6MHz oscillation is not shown properly. I have confirmed that it is working fine.
- Timing from 90% VCC (2.97V) on VCC to V(IT)+ (1.8V) on reset



## XTAL1 Input Pin


- Overdriven
- Within max operating range






### Upstream Port 0

 R33 and R34 on TUSB2036 side (PD0 and PM0)




#### Downstream Port 1

 R35 and R36 on flash drive side




### Downstream Port 1

 R35 and R36 on flash drive side



#### Downstream Port 2

- R2 and R4 on ADuM3160 side
- I did not attempt to capture a single transaction like for port 1 (previous slide)



### Downstream Port 2 After Isolator

 R3 and R5 on FTDI IC side (on another schematic sheet)

