# TAS2562HYFPR – Debug Update

12th November, 2019

### **TAS2562HYFPR** | Summary of Reported Issues

Reported Issue	Debug Update	Screen Status	Issue Status from TI
OC flag set, stops playing audio	<ul> <li>TI identified the root cause to be higher GREG impedance on some devices.</li> <li>Higher GREG impedance along with &gt;200pH board inductance causes the issue.</li> </ul>	<ul> <li>Screen added in FT to filter out devices with higher impedance.</li> <li>Screen gives margin of up to 4nH inductance on GREG.</li> </ul>	Closed in September including screen added.
Intermittent audio cut-off	<ul> <li>Issue debugged to wrong memory pointer initialization.</li> </ul>	<ul> <li>New screen ensures 100% coverage on memory.</li> </ul>	Closed in October including screen added.
Audio POP noise	<ul> <li>I2S output was intermittently corrupted due to glitches.</li> <li>Algorithm is supposed to filter out glitches.</li> <li>Algorithm update needed at Customer system to take care of this.</li> </ul>	■ NA	Closed in September.

#### TAS2562HYFPR | GREG Issue

- GREG design has been done for parasitic inductance of upto 4nH
  - o GREG needs to support up to 4mA current to deliver max power in Class-D under datasheet conditions
- Earlier screen in FT was with lower current(~1mA) under tester conditions
  - This corresponds to 4mA current under datasheet conditions
  - Devices which are marginal can have issues with systems with higher parasitic inductance
- Additional stringent test added, screens for 4mA DC current capability on all devices
  - Allows the device to support maximum designed parasitic inductance of 4nH
  - o The corner case devices which had lower current capability will also get screened out with the new program
  - Provides margin on the customer system which has ~2.6nH(2.1nH board routing + ~500pH of ESL) of parasitic inductance
- Customer Screen is tried and is confirmed to be working for this issue
  - o The factory screen that is added also ensures that the device works in the actual system scenario

#### TAS2562HYFPR | TI Screen Update

- TI screens devices based on GREG Voltage with 4mA Load Current
  - 4mA is higher than maximum expected loading on GREG by device.
  - Failing Units because of higher impedance show much lower voltage on GREG as compared to good devices.
  - This is used as a screen mechanism by TI to weed out bad devices.
  - Design is verified to work with minimum GREG-PVDD voltage of 1.9V where as Test Screen is added at 2.28V to give margin.
  - TI has verified this screen on multiple wafers and screen is working as expected

## **TAS2562HYFPR** Intermittent Audio cut-out

#### **Summary**

- Issue is related to incorrect memory pointer being queried
  - This is because of small(<0.1% memory) uncovered in FT.</li>
  - On good devices, issue is never expected to be seen
  - On failing devices, run to run variation is observed
- Following are the two different screens added in FT to catch failing devices.
  - o 10 individual runs to load/read the pointer are being done in FT to catch this issue
    - In every run, pointer is read back and compared to expected value. Any run fail is screened out.
  - In addition to this, rest of the memory if fully covered in FT.
    - Memory Screen is updated to ensure 100% coverage on memory.

## **End of Slides**