Wake On Proximity

MSP430

CapTlvate

March, 2019



CapTivate Library WOP Limitation

- With the current library, user can only use WOP function with one time cycle.
- The FSM can scan all 4 blocks without waking up the CPU.
- Changing time cycle will require waking up the CPU.



Use Cases 1

• Self mode elements group together as one self WOP sensor





3

- Hardware: CAPTIVATE-BSWP board
- Goal: wake up from all 8 buttons.
- Step 1: Create a 8 buttons sensor (BTN) and an virtual sensor (PRX) as wake-on-proximity sensor
- Step 2: Since the BTN sensor uses all 4 blocks, make sure the PRX sensor also has 4 elements use 4 blocks. It is important to make sure the PRX sensor uses the same blocks as the BTN sensor for calibration purpose. If the BTN sensor only uses 3 blocks then the PRX sensor only needs 3 elements for 3 blocks.



Compile Time Options		
Wake On Proximity Sensor	PRX	V

Step 3: In main.c, change all the PRX sensor CAP IO assignment to match with the BTN sensor.

PRX sensor is a virtual sensor for BTN sensor so we need to make sure PRX sensor only assign elements to BTN sensor CAP IOs. Currently CDC does not allow you to assign 2 RX to the same CAP IO in self mode, we will need to add this feature.

• Step 4: Make sure to enable and activate all the element for BTN sensor when calibrating the PRX sensor since we are using PRX sensor as a virtual sensor for BTN sensor. In CAPT_Manager.c file CAPT_calibrateUI function.





5

• Step 5: Make sure to enable and activate all the element for BTN sensor when update the PRX sensor since we are using PRX sensor as a virtual sensor for BTN sensor. In CAPT_Manager.c file CAPT_updateUI function.



Texas Instruments

Step 6: In CAPT_App.c, make sure to enable and activate all the BTN sensor elements before starting wake on proximity mode and deactivate the BTN sensor after stopping the wake on proximity mode.
 To enable and activate all the BTN sensor elements: MAR_CAPT_fenceSensonT0(aSelf_RETN):

To enable and activate all the BTN sensor elements: MAP_CAPT_forceSensorIO(eSelf,&BTN);

To deactivate the BTN sensor: MAP_CAPT_initSensorIO(&BTN);

```
CAPT_stopWakeOnProxMode(&CAPT_WAKEONPROX_SENSOR, 0);
MAP_CAPT_initSensorIO(&BTN);
```





• Mutual mode elements group together as one mutual WOP sensor





8

- Hardware: CAPTIVATE-PHONE board
- **Goal:** wake up from all 12 buttons.
- Step 1: Create a 12 buttons sensor (BTN) and an virtual sensor (PRX) as wake-on-proximity sensor
- Step 2: Since the BTN sensor uses all 4 blocks, make sure the PRX sensor also has 4 elements use 4 blocks. It is important to make sure the PRX sensor uses the same blocks as the BTN sensor for calibration purpose. If the BTN sensor only uses 3 blocks then the PRX sensor only needs 3 elements for 3 blocks.



	Controller		Sen	sors
Port	Use Mode	Parallel Gro	BTN	PRX
CAP0.0	Unrestricted	B0	RX00	RX00
CAP0.1	Unrestricted	B1	TX00	
CAP0.2	Unrestricted	B2	TX01	
CAP0.3	Unrestricted	B3	TX02	
CAP1.0	Unrestricted	B0	RX01	RX01
CAP1.1	Unrestricted	B1		
CAP1.2	Unrestricted	B2		
CAP1.3	Unrestricted	B3		
CAP2.0	Unrestricted	B0	RX02	RX02
CAP2.1	Unrestricted	B1		
CAP2.2	Unrestricted	B2		
CAP2.3	Unrestricted	B3		
CAP3.0	Unrestricted	B0	RX03	RX03
CAP3.1	Unrestricted	B1		
CAP3.2	Unrestricted	B2		
CAP3.3	Unrestricted	B3		TX00

Compile Time Options		
Wake On Proximity Sensor	PRX V	

- Step 3: In main.c, change all the PRX sensor CAP IO assignment to match with the BTN sensor.
- PRX sensor is a virtual sensor for BTN sensor so we need to make sure PRX sensor only assign elements to BTN sensor CAP IOs. Currently CDC does not allow you to assign 2 TX to the same CAP IO in mutual mode, we will need to add this feature.

_ ,	PRX_E03.ui8TxBlock = 0; PRX_E03.ui8TxPin = 1;	🦆 Texas Instruments
<pre>extern tElement PRX_E03;</pre>	PRX E02 μ i8TxPin = 1.	
<pre>extern tElement PRX_E02;</pre>	<pre>PRX E02.ui8TxBlock = 0;</pre>	9
<pre>extern tElement PRX_E01;</pre>	<pre>PRX_E01.ui8TxPin = 1;</pre>	
<pre>extern tElement PRX_E00;</pre>	<pre>PRX_E01.ui8TxBlock = 0;</pre>	
	<pre>PRX_E00.ui8TxPin = 1;</pre>	
	PRX_E00.ui8TxBlock = 0;	

• Step 3: Make sure to enable and activate all the element for BTN sensor when calibrating the PRX sensor since we are using PRX sensor as a virtual sensor for BTN sensor. In CAPT_Manager.c file CAPT_calibrateUI function.





• Step 4: Make sure to enable and activate all the element for BTN sensor when update the PRX sensor since we are using PRX sensor as a virtual sensor for BTN sensor. In CAPT_Manager.c file CAPT_updateUI function.





 Step 5: In CAPT_App.c, make sure to enable and activate all the BTN sensor elements before starting wake on proximity mode and deactivate the BTN sensor after stopping the wake on proximity mode. To enable and activate all the BTN sensor elements:

To deactivate the BTN sensor: MAP_CAPT_initSensorIO(&BTN);

```
CAPT_stopWakeOnProxMode(&CAPT_WAKEONPROX_SENSOR, 0);
MAP_CAPT_initSensorIO(&BTN);
```

