


I have made inquiries several times, but after that, I was able to perform additional verification, so I will report it.

Charging circuit for products under development [circuit diagram]



Preference pin status

ILIM:400mA	(Problem occurs even at 500mA)	VSET:4.1V	(The problem occurs even at 4.2V)
------------	--------------------------------	-----------	-----------------------------------

Environmental test results:


Product condition:	30deg: NG, 28deg: OK
Charging board and battery only:	43deg: NG, 42deg: OK

Consideration: The battery pack has a thermistor for temperature measurement, and if the temperature read by bq25616j exceeds 45deg, an error (STAT-pin: 1KHz) will occur.


Battery voltage graph during product testing

Constant temperature bath 28deg: voltage drop is seen when fully charged → normal

Constant temperature bath 30deg: No voltage drop when fully charged → error




45deg



Using a battery that is almost fully charged,

A: Change ILIM to 400mA/500mA
B: Change VSET to 4.1V/4.2V
C: Replace the thermistor with a resistor to change the battery pack temperature




500mA~3200mA 300mA~3000mA

TEST	SET-DEG(°C)	resistance(kΩ)	VSET(V)	300mA - 3200mA	300mA - 3200mA	STAT-PIN	RESULT	Consideration
				I _{LM} (mA)	I _{CHG} (mA)			
1	46	4.7	4.1	398(1.2kΩ)	403(1.68kΩ)	1kHz	NG	STAT-PIN = ERROR(1KHz)
2	46	4.7	4.2	398(1.2kΩ)	403(1.68kΩ)	1kHz	NG	STAT-PIN = ERROR(1KHz)
3	46	4.7	4.2	525(910Ω)	403(1.68kΩ)	1kHz	NG	STAT-PIN = ERROR(1KHz)
4	25	10	4.2	525(910Ω)	403(1.68kΩ)	Hi	OK	within 30 minutes STAT-PIN = Lo → Hi
5	25	10	4.1	525(910Ω)	403(1.68kΩ)	Hi	OK	within 30 minutes STAT-PIN = Lo → Hi
6	41	5.6	4.1	525(910Ω)	403(1.68kΩ)	Hi	OK	within 30 minutes STAT-PIN = Lo → Hi
7	52	3.9	4.1	525(910Ω)	403(1.68kΩ)	1kHz	NG	STAT-PIN = ERROR(1KHz)
8	63	2.7	4.1	525(910Ω)	403(1.68kΩ)	1kHz	OK	Immediately after power on STAT-PIN = 1kHz
9	44	5.1	4.1	525(910Ω)	403(1.68kΩ)	1kHz	NG	STAT-PIN = ERROR(1KHz)
10	-1	30	4.1	525(910Ω)	403(1.68kΩ)	1kHz	OK	Immediately after power on STAT-PIN = 1kHz


Casio's opinion

with the temperature profile during charging. The problem occurred between T3 and T5, and changing the ILIM and VSET settings did not solve the problem.



(STAT端子：充電状態表示)

CHARGING STATE	STAT INDICATOR
Charging in progress (including recharge)	LOW
Charging termination (top off timer may be running)	HIGH
Sleep mode, charge disable, boost mode	HIGH
Charge suspend (input over-voltage, TS fault, safety timer fault or system over-voltage)	Blinking at 1 Hz



We don't want the bq25616j STAT-PIN to give an error in the temperature range between T3-T5 and keep the battery voltage as set by VSET. I would like to know the cause of this error. Also, please provide a means to prevent this error from occurring.

At the very least, we need to stop this error in order to bring the product to market, and it is difficult to add error protection to our circuits. The time from making a prototype to mass production is limited, so we request that you respond as soon as possible.

At that time, there was no IC with equivalent functions other than bq25616j. I hope you find a way to stop this error.

thank you.