

## 1 Questions to TI

### 1.1 Summary

#### 1.1.1 Summary


There is an output intermittent issue related to common mode noise on the input voltage at Vblk observed with the fly-back controller using TI p/n: UCC28700QDBVRQ1. When DC input (Vblk) contains common mode noise due to boosting PWM operation at 470 kHz, output voltage become unstable or drop out and drop in (See waveforms)

#### 1.1.2 Question to TI FAE

- 1) Please go over this report. Any comments are appreciated
- 2) What are the common reasons for the fly-back switching become irregular?
- 3) Sometime DRV signal turn on Primary winding longer than other times. What condition determine the turn on duration?
- 4) Please let me know if you have any question

Thank you,  
Dung Do,  
Electrical Engineer,  
[dung@aveox.com](mailto:dung@aveox.com)

### 1.2 Setup




Vin: Red & Black wires, two scope probes vs CHS\_GND

Vout: White & Black, two scope probes vs float returns connected together (measured differentially)



Vout is programmed to 12V and a resistor load of 30 Ohms is connected to the output

Vaux: Green & Black, two scope probes vs float return connected together (measure differentially)

### 1.3 Fly-back board Schematics



## 1.4 PCB Layout



## 1.5 Instruments

Scope probe: Yokogawa 700929: 10 M $\Omega$ /approx. 18 pF

Scope trace saved in Yokogawa #2: HD\_0/Dung/1.5kv/20190801\_144757\_080.WDF

## 1.6 Observation



Ch4: Vdc+ vs CHS (input +)

Ch5: Vdc- vs CHS (input-)

ChR9Vin: Voltage drop across input (measured differentially)

ChR7+12: +12Vdc (Output voltage measured differentially)

ChR1Aux: Voltage across Auxiliary winding (measured differentially)

Waveform show +12V output when input is boosted up



Zoom of above in non-boosting section showing Vout and Vaux operate normally



Zoom of above in boosting section showing Vout and Vaux drop -in and drop-out



Further zoom in at drop-out