



You can see here that: VHB may be dropping below UVLO. We have no high state pulses lesser than 700uS (1016uS shown) @ HI input.





Also, the voltage @ VBUS goes up to 1.46V, which correspond to Vgs threshold of the used MOSFET transistor with HB @4.5V, however the charge pump circuit should increase HB up to HS+4.5V in order for the driver to keep HI MOSFET ON.

We did:

Increased C81 to 0.22uF with pretty much the same results.

Removed R49 (left that open so only the internal bootstrap diode was used) VBUS dropped to 1.28-1.44V

Shorted R49, VBUS went up to 1.48V roughly.

My conclusion is that the charge pump circuitry is not working

PD the HI input is driven by a 3.3V circuitry, I have never measured a voltage greater than 3.8V at that pin.