

UCC25630-1EVM-291 (IC changed to UCC256302) LLC load transient response evaluation

With the combination of PFC and LLC (input AC100 V, output DC 12 V 10 A condition), LLC load transient response evaluation of load sudden change rate 0 \leftrightarrow 100%, duty 50%, **10 Hz** in CC mode and CR mode was done.

As a result, immediately after the LLC output suddenly changes from 0% load to 100% load, the output was stopped.

I think this is malfunction of LLC evaluation board.

So the output transient response test was performed again only on the LLC evaluation board.

As a result, similar trouble symptoms occurred again, so I show the test conditions and indicates a defect observed waveform.

When evaluating with only LLC, the problem of load fluctuation occurred in case of the input voltage is higher than DC 390 V.

When I test it with PFC, I think that this symptom is likely to occur at the timing at the voltage rises due to load fluctuation of PFC output.


This problem is caused by whether there is a problem in the circuit setting of the LLC evaluation board or due to limit of IC ability.

What do you think about?

1. LLC load sudden change test 1 (when **R14 = 2 MΩ** mounted)

<Test condition> LLC input voltage _ **DC 405 V**, LLC output: DC 12 V 10 A (rated load)

12V output load sudden change: 2A (20%) ⇔ 12 A (100%), **sudden change cycle: 10 Hz**, duty: 50%




Blue FB voltage [1V/div]
 Red LLC. vin [100V/div]
 Green LLC. Io [5A div]
 Pink LLC. Vout [2V/div]

H: [2msec (1sec)/div]

2. LLC load sudden change test 1 (when **R14 = 840kΩ** board **default** mounted)

<Test condition> LLC input voltage _ **DC 405 V**, LLC output: DC 12 V 10 A (rated load)

12V output load sudden change: 1A (10%) \Leftrightarrow 12 A (100%), **sudden change cycle: 10 Hz**, duty: 50%



Blue FB voltage [1V/div]

Red LLC. vin [100V/div]

Green LLC. Io [5A div]

Pink LLC. Vout [2V/div]

H: [1msec (2sec)/div]