


UCC256302 frequency stability issue

Problem description

Output noise from LLC converter is unstable when using UCC256302 IC as shown in plot below.





The original circuit was modified to try to identify to noise source. The modifications are described below.



- To eliminate the possibility of control loop issue, the IC is run open loop with just 85k 0603 resistor and 2.2nF 0603 ceramic capacitor from FB to GND.
- To eliminate the possibility of layout issue, a copper foil plane is made on top of the IC body and connected directly to GND pin. The following pins are connected to this ground plane and decoupled with ceramic capacitors.
LL/SS, BW, VCR, ISNS, BLK, VCC.
- VCR is run in oscillator mode (no feed from resonant capacitor voltage)
- RVcc has additional decoupling 100nF + 1uF, + 4.7uF + 10uF ceramic capacitors
- HV pin is lifted to eliminate any capacitance (as per layout guidelines)

See following pages for schematic and physical layout.




Even with these modifications, significant frequency jitter can still be observed.

Schematic and physical structure





Waveforms

 <p>0.1 μs 100 V</p> <p>100.0 μs</p>	<p>Switching edges</p>
 <p>1 μs 100 V</p> <p>353 supps</p> <p>100.0 μs</p>	<p>Switching jitter at 100μs delay from trigger.</p>
<p>25-Sep-19 15:30:59</p>  <p>10 μs 50 mV</p> <p>100 μs</p>	<p>CH1 = Output ripple</p>

