

Failure Analysis Report



TI Information - Selective Disclosure

Device Analysis Services

FA QEM-CCR-1906-00715

ACTION-0303272

Customer:	WINTECH (DSTR)	Assy Site:	TAI
Customer Tracking ID:		Fab Site:	CU3
Customer Part ID:		Technology:	LBC5
Customer Contact:	Yi Dary	Analyst:	Rang Cheng
Device Type:	DRV8840PWPR	TI Contact:	Jerry Xiao
		Qty Submitted:	1
Flow Type:	Customer Return	Date Submitted:	2019-06-26
Reviewer:	Chaplin Tu	Approval:	Rang Cheng

Summary	
Failure Analysis	Results
Customer Reported Failure Mode	Issue type: Electrical Issue type details: Chip burned out, part of the pin short circuit. Other details: One chip was returned by a Korean customer, Pins 3,5and 6 are short to the ground. The other 2pcs were burned out in the company's internal product test. The chips returned by Korean customers must be given a more detailed report.
TI Failure Description	Short failure was verified at pin3, 5, 6, 10 and 12-14. Open failure was verified at pin4(VM), pin7-9 and pin11(VM).
What effect does the defect or damage cause?	Short failure was verified at pin3, 5, 6, 10 and 12-14. Open failure was verified at pin4(VM), pin7-9 and pin11(VM).
Where and what is the defect/damage?	EIPD was observed.
Did the identified physical defect/damage explain the TI reported failure mode?	Yes.

TI Unit #	Cust. Unit #	Lot Trace Code	Symbolization	Wafer Fab Lot #	Assembly Lot #
1		89ALPYT		8171244	8897232TW8

Failure analysis is performed as a technical service to both customers and users of microcircuits manufactured by Texas Instruments, Inc. (TI). Failure Analysis Reports and Quality Tracking System (QTS) Reports are considered proprietary to TI, and are for selective disclosure to third parties only as authorized by TI. Consequently, they are marked, "TI Information - Selective Disclosure."

The information conveyed in these reports does not alter TI's warranty or other terms and conditions of sale. Unless otherwise specifically noted, the report is not an authorization to return products. Application advice is provided "AS IS." The information provided herein may change if additional facts are discovered.

- **Customer Reported Problem Description:**

Issue type: Electrical | Issue type details: Chip burned out, part of the pin short circuit. | Other details: One chip was returned by a Korean customer, Pins 3,5and 6 are short to the ground.

The other 2pcs were burned out in the company's internal product test.

The chips returned by Korean customers must be given a more detailed report.

- **TI Problem Description:**

Short failure was verified at pin3, 5, 6, 10 and 12-14. Open failure was verified at pin4(VM), pin7-9 and pin11(VM).

- **Package Analysis:**

- **External Package Examination:**

The returned unit was inspected under microscope. Missing leads were observed from external package.




Fig.1: Optical view of the returned unit.

- **X-Ray Analysis:**

The returned unit was inspected by X-ray. Broken leads and bonding wires were observed from internal package.




Fig.2: X-ray view of the returned unit.

- **Scanning Acoustic Microscopy (SAM):**

CSAM was performed on returned unit. Delamination was observed over die surface of returned unit.




Fig.3: CSAM image of returned unit.

- Electrical Characterization:**

Curve trace analysis was performed on the returned unit. Short failure was verified at pin3, 5, 6, 10 and 12-14. Open failure was verified at pin4(VM), pin7-9 and pin11(VM).




Fig.4: I/V curve image of returned unit. **Correlation unit (blue) & returned units (red).**

- **De-capsulation and Internal Optical Inspection:**

The returned unit was chemically de-capsulated with fuming nitride acid. EIPD (Electrically induced physical defect) was observed on die surface.




Fig.5: Optical image of the returned unit after de-capsulation.

- **Observation:**

EIPD (Electrically induced physical defect) was observed.

Short and open failure was caused by EIPD.

Note 1: Due to digital image capture, the magnification is not calibrated nor is the aspect ratio maintained. Not all tools provide a means recorded in the image for calibrating the measurements. When a calibration marker is supplied in the image, the measurements may be calibrated in the direction of the marker