## Hi Fleenor,

We probed the CAN\_H and CAN\_L lines for both boards and observed the following results:

## 1. F28P65X to F28P65X Communication:


Two F28P65X devices were connected, and their CAN signals were observed.
The communication appeared to be functioning as expected.





# 2. AM2634 to AM2634 Communication:

Two AM2634 devices were connected, and their CAN signals were observed.
The communication appeared to be functioning as expected.





## 3. F28P65X to AM2634 Communication:

- When attempting communication between F28P65X and AM2634, we encountered two different scenarios:
  - F28P65X transmitting to AM2634:
    - The **F28P65X** continuously attempts to send data to the **AM2634**.
    - However, the same transmission process is repeated multiple times until it reaches a timeout, at which point the communication fails.








# ■ AM2634 transmitting to F28P65X:

■ When the **AM2634** attempts to send data to the **F28P65X**, the AM2634 reports an **MCAN\_INTR\_SRC\_PROTOCOL\_ERR\_DATA** error, indicating a protocol error in data transmission.





These observations suggest a potential **compatibility issue** between the **F28P65X and AM2634** in CAN communication. Further debugging may be needed to analyze the potential differences in CAN protocol implementation between the two devices.