

## **Product Return: CPR241104517**

## Contact

Ankush Tiwari
Ambetronics Engineers
17-B, Tarun Industrial Estate,
Mogra Pada, New Nagardas Road,
Andheri East , Mumbai Maharashtra
400069 IN
+ 91(22) 61673031
rnd4@ambetronics.com

TI orderable part number: TMDSEMU110-U

Customer part number:

Customer Requesting: Product replacement

Purchased from: TI Store

Sales contact name: HETAL Waghmare

Was the board containing suspect TI part

manufactured by 3rd party?

Board manufacturer name:

Board manufacturer site/location:

Board manufacturer contact email address:

Order number: 5930569505

Distributor name:

Distributor site/location:

Distributor contact email address:

Distributor tracking# / SCAR#:

Customer reference/tracking #: CS2419915

Sales order number (SO#): 5930569505



Purchase order number (PO#):	5930569505		
Delivery document number (DN#):			
End customer name:	HETAL Waghmare Ambetronics Engineers purchase@ambetronics.com		
End customer's company name:			
End customer's email address:			
Return details			
Priority of this return :	Standard : Development of Product Stop		
Application:	Inhouse Testing		
Customer failure location:	Incoming Inspection		
Type of issue :	Electrical: Functional Issue		
Provide TI component level failure description based on customer verification results. :	Hi Team, As per your suggestion I have discus sed with E2E forum Expert and their review al so is same as our the Debugger XDS110 is fault y please provide replacement and fault Debugg er return as soon as possible I am sharing t he link where we have discussed with E2E foru m Expert . https://e2e.ti.com/support/microco ntrollers/arm-based-microcontrollers-group/arm -based-microcontrollers f/arm-based-microcontrollers-forum/1395740/tmdsemu110-u-xds110-debug -probe/5341205		
Part Details:			
Total failed quantity:	1		
Desired return quantity:	1		
Total units run :	1		

## \*\* TEXAS INSTRUMENTS

Failure rate (ppm):		1000000
Is the suspect TI part used in more than location on the circuit board? : How many locations? :	one	No
Which locations are causing the issue?	:	
Is this a new application?:	No	
When did production of this application	start?:	08/2023
Was the application/design changed or recently (within the last year)?:	No	
Did the same issue occur in the past?:	No	
Provide the reference TI QEM#.:		
U	nit 1	
Customer unit ID:		
Batch Number:		
Lot trace code:		
Ship trace code:		
Programmable products		
Are you returning a programmable or RF low power device? :	No	
Is the suspect TI part protected by a Security Key Code?:		
Which firmware version is used?:		
Wireless Connectivity		

radio products:

## \*\* TEXAS INSTRUMENTS

Suspect TI Part Register Settings?:
Failing Radio (BT/FM/WLAN/GPS):
Failing pin(s):
Failing parameter (RF or power management):
Failing modulation/rate (if applicable):
Failing channel/ frequency:
Which firmware version is used?:
MSP430/MSP432 Microcontrollers :
Is the JTAG access disabled?:
Please provide the customer code :
Failure conditions :
Temperature (°C): 25
Mileage (km):
Frequency (Hz):
Vcc/Vdd (V):
Vout (V):
Failure conditions to a specific usage :



What is the condition of the suspected failing TI part(s)?:	Repeatable	
Was the observed issue verified on suspect TI part level outside the application? :	Yes	
Was the suspect TI part installed onto another passing board causing that board to fail (A-B-A swap)?:	No	
Did replacing the suspect TI part resolve the issue?:	Yes	
Files:		