Bq24079 start charging after /CE goes High, but charging is terminated immediately. This abnormal operation is not confirmed every time on the same device. Our customer is confirmed this problem at multiple samples. Can you estimate the cause of this problem?

Device: bq24079 ICHG: 300mA

VBAT: 4.0V at measuring these waveform

