

TPS61160

The dispersion of start time is due to the CTRL pin of PWM duty cycle.











