


## STANDARD SETUP



## FOR TEST PURPOSE ONLY

Change third party SPE-ETHERNET converter with DP83TD510E-EVM => same issue