

Fix old SPI Flash -- Add AT25DN512C-SSHF-T
Fix 5V reg VOS line (goes after inductor)
Fix enable line for all*
Fix 10uF Cap size after Inductor
Fix reset line to add all GRST including HUB
Fix input power capacitor sizing (6.3V is too small)

