





# Schematic



# Troubleshooting – Ethernet waveforms

- Start of frame
- Plots were taken with diff. probe at 850mV level, clipping of waveforms



Preamble appears to be incorrect