

All other signals are from A to B is required and working properly.

Issue: OTG\_ID has to be B to A, by mistake this has been connected as A to B. During operation we are seeing this is working for our use case without any issue. Only concern is whether this usage will have any adverse affect on life of the buffer of particular pin or IC