

Sequence

Normal Conditions

In operation:

- 1. Press Send-SW.
- 2. Tx-LED is Blink.
- 3. Serial data output from GDO2 port.
- 4. Rx-LED blinking.
- 5. Motor rotates.

At reset:

- 1. Press RESET-SW.
- 2. Rx-LED will light up for 1 second.
- 3. Normal Conditions.

Error Conditions

In operation:

- 1. Press Send-SW.
- 2. Tx-LED is Blink.
- 3. Noise output from GDO2 port.
- 4. Rx-LED is not light.
- 5 . Motor dose not rotates.

At reset:

- 1. Press RESET-SW.
- 2. Rx-LED will light up for 1 second.
- 3 .But, Not revive.