



There was a problem that the synchronization frequency and SW shifted.

Vin=24V Vout=5.5V