

Is there any problem with setting the register(R5) of EN pin to 0 Ω ?