

## LMR14050-Q1 Interference issue

## **Problem Description**

- LMR14050-Q1 of TI (Current : 5A max)
  - Location No : IC601
  - Observed ringing, overshoot and undershoot at rising and falling edge
  - Especially FM reception sensitivity can not meet customer spec

## **Problem Description**





## Schematic

