



Application image



- Hot plugin
- It will be connected in the order of GND => VIN 1 and VIN 2.
- While the pad terminal is sliding there is a possibility that the contact of GND or VIN 1, VIN 2 is momentarily separated. Is there a possibility of problems with TPS 22966?

