


Probing UART Tx from CC2652RB
shows same data loss as capturing UART
data in Linux UART driver

V2.40 SDK – OK
V3.10 SDK - NOK



If CC2650 with BLE2.2.1 fails
If CC2652RB with SDK 3.1 ok