



OPA 1632 GAIN = 1

Add 2 pole filter for DAC output filter requirements

OPA 1632 are floating 0v middle of +/- rails ? Vcom not connected

high current load on - or + when gnd connected to board & unpredictable results..

Pin 4 of OPA1632 + output connected to + Left input of TPA6120A2RGYT
Is this the wrong way around ?

U3B
3 NC 4 NC 5 NC 6 1K
TI (Texas Instruments) TPA6120A2RGYT

Title HeadphoneDriverCard		
Size A3	Number version 1	Revision
Date: 12/04/2017	Sheet of	
File: headphone3.SchDoc	Drawn By: Ben Biles	