



CLS03 was stopped production from supplier.

So D2 was changed from CLS03 to SK106 or SK108 or SK1010