

TAS2563 Known Issues



Version: 3.0.2

Release Date: 19-Mar-2020

S.No	Issue Description	Work Around
1	Starting audio recording / playback when I2C writes are in progress may cause the playback device to be unresponsive	Audio recording / playback can be started after I2C writes are complete
2	GUI will not connect automatically with the EVM	Connect button can be used to connect EVM and the app
3	Support for Inter Channel Limiter Alignment (ICLA) is not available in ROM mode.	NA
4	End System Integration doesn't support switching script	NA
5	Speaker Normalization is not supported for this release	NA
6	Ultrasound (96 KHz) is not supported for this release	NA
7	Warning popup appears saying different version of EVM Connected	Ignore the popup and proceed further
8	With 3.3 V IOVDD (J15 in XMOS Mother board) speaker characterization might not work properly.	For speaker characterization, use 1.8V IOVDD.
9	Temperature might be ~9 degrees away from the limit when the Tmax is 80 or above during speaker characterization	NA