

Initially observed that 1.1V is rising along with 3.3V. (Is it a problem ?) Hence we added delay in enable of 1.1V so that the output starts rising only after 3.3V settles to final value.