


Import&build: CCS project "GPIO_LedBlink_idkAM574x_armTestProject"



Check behavior




Copy & modify: boot.asm -> delete Debug & Build



Modify here

Copy from "C:\fi\forall bios_6_73_01_01\forall packages\forall gnu\forall targets\forall arm\forall rts\forall 7A\forall boot.asm"

Check behavior



We can find proper LED blink behavior, after resume.