I am using [BP-CC3301MOD, LP-AM243] to check the operation of a sample project (cc3xxx_network_terminal), but an error occurs.

Please tell me the cause of the error and how to fix it.

1. environment


software


CCS 12.8.1.00005 cc33xx_mcu_package_R5 mcu_plus_sdk_am243x_08_05_00_24 Python 3.13.4


Evaluation Kit

BP-CC3301MOD Rev E1 LP-AM243

2. Build







3. EVM Setup

Reference sites


https://software-dl.ti.com/mcu-plus-sdk/esd/AM243X/08_05_00_24/exports/docs/api_guide_am243x/EVM_SETUP_PAGE.html

Cable Connections


Power Indication LEDs




Setup UART Terminal



Windows Device Manager






Flash SOC Initialization Binary




POWER-ON the AM243X-LP




Close the UART terminal 📃 Console 📳 Problems 🚍 Memory Allocation 🚍 Stack Usage 🔗 Search 🌼 Call Hierarchy 🦃 Terminal 🗶

flash the SOC initialization binary to the LP



ERROR

Please tell me the cause of the error and how to fix it





SOC Initialization Using CCS Scripting

Environment Variable

MCU_PLUS_SDK_AM243X_PATH

C:\fi\f\mcu_plus_sdk_am243x_08_05_00_24






Restarted CCS


NOBOOT MODE




POWER-ON




AM243x_XDS110.ccxml




Launch the target configuration created with Create Target Configuration - □ X cc33xx_mcu_example_2 - cc3xxx_network_terminal/main.c - Code Composer Studio File Edit View Navigate Project Run Scripts Window Help Q 🔡 🛱 😼 🖺 Project Explorer 🗴 📄 🔄 🍞 🖇 🗖 🔲 🖟 main.c 🗴 50 void *myrealloc(void * p, size_t size) > 👸 ble_host_nimble 🖫 🗶 🗳 🗏 51 { > 👺 ble_interface 52 return 0; type filter text > 👑 cc3xxx_network_terminal 53 } > 👺 lwip > 📂 Projects 55 void freertos_main(void *args) 🗸 🗁 User Defined > 👑 wifi_host_driver 56 **{** 57 R AM243x XDS110.ccxml > 👑 wifi_platform_cc33xx network_terminal_entry(NULL); Rew Target Configuration > 👺 wifi_stack_interface 58 vTaskDelete(NULL); Import Target Configuration 60 } Delete 61 62 Rename 63 int main() 64 { Refresh Launch Selected Launch Selected Configuration 🖃 Console 🗶 🔣 Problems 🗧 Memory Allocation 🚍 Stack Usage 🔗 Search 🌼 Call Hierarchy Set as Default **×** | ↓ **û** ⑤ Link File To Project CDT Build Console Properties 8 cc33xx_mcu_example_2 - cc3xxx_network_terminal/main.c - Code Composer Studio <u>F</u>ile Edit <u>V</u>iew <u>P</u>roject <u>T</u>ools <u>R</u>un Scripts <u>W</u>indow <u>H</u>elp □ □ (x)= Variables of Expressions 1010 Registers on Breakpoints × 🗸 🚳 AM243x XDS110.ccxml [Code Composer Studio - Device Debugging] 💣 🔻 🗶 💥 🚜 📲 Texas Instruments XDS110 USB Debug Probe_0/MAIN_Cortex_R5_0_0 (Disconnected: Unknown) Condition Identity Name Count Yew Texas Instruments XDS110 USB Debug Probe_0/MAIN_Cortex_R5_0_1 (Disconnected: Unknown) Texas Instruments XDS110 USB Debug Probe_0/MAIN_Cortex_R5_1_0 (Disconnected: Unknown) Texas Instruments XDS110 USB Debug Probe_0/MAIN_Cortex_R5_1_1 (Disconnected: Unknown) Texas Instruments XDS110 USB Debug Probe_0/DMSC_Cortex_M3_0 (Disconnected: Unknown) Texas Instruments XDS110 USB Debug Probe_0/BLAZAR_Cortex_M4F_0 (Disconnected: Unknown)



load DMSC FW and initialize the SOC






4. Sample run

There was an error in the [3. EVM Setup], but I tried running the sample project.


OSPI BOOT MODE



POWER ON



► BP-CC3301MOD Rev E1



71

72

73 74

75

cc3xxx_network_terminal

Console X @ Scripting Console 🔗 Search

MAIN_Cortex_R5_0_0: AM2434_ALX

/* This task is created at highest priority, it should create more tasks and then delete itself */
gMainTask = xTaskCreateStatic(freertos_main, /* Pointer to the function that implements the task. */

NULL,


"freertos_main", /* Text name for the task. This is to facilitate debugging only. */

/* We are not using the task parameter. */

MAIN_TASK_SIZE, /* Stack depth in units of StackType_t typically uint32_t on 32b CPUs */

MAIN_TASK_PRI, /* task priority, 0 is lowest priority, configMAX_PRIORITIES-1 is highest lwip is 7 */

■ □ ▼ □ ▼ □ □



```
COM19:115200bps - Tera Term VT
ファイル(\underline{F}) 編集(\underline{F}) 設定(\underline{S}) コントロール(\underline{O}) ウィンドウ(\underline{W}) ヘルプ(\underline{H})
INFO: Bootloader_runCpu:155: CPU r5f1-1 is initialized to 800000000 Hz !!!
INFO: Bootloader_runCpu:155: CPU m4f0-0 is initialized to 400000000 Hz !!!
INFO: Bootloader_loadSelfCpu:207: CPU r5f0-0 is initialized to 800000000 Hz !!!
INFO: Bootloader_loadSelfCpu:207: CPU r5f0-1 is initialized to 800000000 Hz !!!
INFO: Bootloader_runSelfCpu:217: All done, reseting self ...
******************* Osprey Network Terminal ***********
*****
                                        ******
                 Version 1.1.0.4
***********************
Available commands:
help
                                  wlan_ap_role_up
                                                   wlan_ap_role_down
                 clear
wlan_sta_role_up
                 wlan_sta_role_down wlan_connect
                                                   wlan_disconnect
                 wlan_get_mac
                                                   wlan_get_ps
                                  wlan_set_mac
wlan_scan
                                  wlan_set_LSI
wlan_set_ps
                 wlan_set_pm
                                                   wlan_start
                 ble_adv_cfg
                                  ble_adv_enable
wlan_stop
                                                   ble_scan_cfg
ble_scan_enable
                                  ble_disconnect
                                                   ble_peers
                 ble_connect
                                  ble_test_mode
                 ble_stop
                                                   calibrator
ble_start
send
                                  socket_show
                                                   kill
                 recv
```

Console X @ Scripting Console 🔗 Search

MAIN_Cortex_R5_0_0: AM2434_ALX

cc3xxx_network_terminal

```
wlan_start
COM19:115200bps - Tera Term VT
                                                                   _ _
ファイル(\underline{F}) 編集(\underline{E}) 設定(\underline{S}) コントロール(\underline{O}) ウィンドウ(\underline{W}) ヘルプ(\underline{H})
INFO: Bootloader_runSelfCpu:217: All done, reseting self ...
*****************************
Version 1.1.0.4
*************************
Available commands:
                                    wlan_ap_role_up
                                                       wlan_ap_role_down
help
                  clear
                  wlan_sta_role_down wlan_connect
                                                       wlan_disconnect
wlan_sta_role_up
                                    wlan_set_mac
                                                       wlan_get_ps
wlan_scan
                  wlan_get_mac
wlan_set_ps
                                    wlan_set_LSI
                  wlan_set_pm
                                                       wlan_start
                                                       ble_scan_cfg
                                    ble_adv_enable
wlan_stop
                  ble_adv_cfg
ble_scan_enable
                                                       ble_peers
                  ble_connect
                                    ble_disconnect
ble_start
                                    ble_test_mode
                                                       calibrator
                  ble_stop
                                    socket_show
                                                       kill
                  recv
user:wlan_start
                                                                                              An error occurred.
[Error] Sciclient event config failed!!!
 SSERT: 72.618150s: ../WiFi_adaptation_layer/wlan_irq_adapt.c:Sciclient_gpioIrqSet:110
 FALSE failed !!!
```

Debug Suspend

