



▪ DLP3010EVM-LC

- Issue : Abnormal Internal Pattern Mode Operation depending on TI FW.

DLP® Pico Display and Light Control EVM




- A) FWSel_DLPC3478_DLPA2005_pm1_i2c0x36_v8p0p0.img → OK
- B) DLP3010EVM-LC_9.0.1.img → It seems to be like Run Once.

▪ DLP3010EVM-LC

- **Question :** Is there no problem when I select "DLP3010EVM-LC_9.0.1"?

Backup Firmware
Update Firmware
Update Flash Image

 Update Flash Image

You can update DLP LightCrafter™ Display firmware with below options:

1. Modify user defined block
2. Modify splash screens
3. Modify display start-up options


If you want to update flash image now, click the get start button below to begin. We'll walk you through the process.

Start >


Select the EVM type _____

DLP3010EVM-LC ▾

Select flash image to update (input) _____

pData\Local\DLPDisplayAndLightControl\DLP3010EVM-LC_9.0.1.img


Select the name of the updated flash image (output) _____

ro\231122_8bit_360fps_3pattern_120Hz_Exp2498_R500G400B1000.img


< Back
Next >