20181218:change AUIDIO_IO from 3.3V to 1.8V

20190108:change FR106 to NC for using I2C instead of SPI to configure the audio codec

20190110:add the factorty test point TPE86 TPE88 for speaker
20190117:change FFB20,FFB21 from BEAD/120ohm to R/0ohm
20190119:change FFB20,FFB21 from R/0ohm to BEAD/120ohm

20190102:add 1uF Cap FC85,FC86,FC87,FC88 connect to GND

20181218:change DVDDIO from 3.3V to 1.8V
20190102:change DVDDIO from 1.8V to 3.3V,and delete FFB24

reserve for Speaker 5V power

20190103:change C1028 from 1nF/0201 to 1nF/0402

20181218:change all U1122 related components to NC

Vout=0.6*(1+R1/R2)=4.97V

20181218:add FR835 for AMP power

Title	PAGE_08 Audio path
Size	Custom
Document Number	Scallop DVT
Rev	0.4
Date:	Tuesday, February 26, 2019
Sheet	7 of 10