Customer Configuration & Results



Clockout0 and Clockout1 are the same configurations.
(frequency=122.88MHz, format=LVDS)

Phase Noise & RMS Jitter results of CLKout0/1





Clockout0 and Clockout1 are the same configurations.
But the results are different.
Why is that ?
Is this because models of additive jitter are different every output ? or is it a bug?