HDC1080 I2C Waveform

Ch1(Yellow)=SDA, Ch2(Green)=SCL,
Ch3(Purple)=Timing signal for 0xFFh data getting is generated by controller.
Ch4(Light blue)=Don't care

1. Measurement start command before 100ms wait time

2. Temp and humid data reading out after 100ms wait time

EOF.