Figure 1. Fully functional button, SPI clk and data



Figure 2. Jitter issue