20180321 – LM20144-Q1 – 1Vout 2A – PROBLEMS.odt



Illustrazione 1: startup - power supply is 5Vin, Vout 1,15V Rload = 0,5ohm



Illustrazione 2: after start transition - it seems that SW doesn't swith never. I can't see switch on SW output -