Unit #2

Insufficient silver epoxy

Top View

Tilt View

Side View