0.89Vout   TPS40425

Is this "shaking" normal operation?
Is there a way to suppress it?