TPS53014 EVM Waveform 1


Specifications Condition

Vin：24V
Vout：5V
Iout：2.3A

Switching waveform became constant.

TPS53014 EVM Waveform 2

Switching waveform became Turbulent.
Is this waveform, the problem with IC operation?
Output voltage accuracy and ripple voltage and load regulation is Influence?