・TPS65910EVM
・USB-TO-GPIO
・USB-TO-USB
　micro cable
・10pin ribbon cable
・PC Windows 7
　・NET Framwork4/3.51
　・LabView ran time

# Block Diagram

jumper setting

jumper setting

TPS65910 EVM

File View I/O Help

I/O Flag 7 | Device Address: | Protocol: I2C | Read All | Write All | Burst Read | Address: | Data:

I/O Error

I/O Subsystem not functional, unable to load firmware version.
Check to see if device is connected.

OK

Register Properties

Register Map

Modes

Log

Get an error even though it has already been connected to the Device.