We suggest pulling down COMP voltage to below 250mV to have no PWM output on UC2843.