# 1 Start Charging HIZ mode by I2C only

VSYS gets driven before the BQ25713 is commanded to enter HIZ mode. So it seems to be necessary to set the controller into HIZ mode with the ILIM_HIZ pin 6.

CH1 VBUS
CH2 VSYS
CH3 VBAT
CH4 ILIM_HIZ

2 Start Charging HIZ mode by I2C only TP5 shorted to TP12

The BATFET is shorted. This seems to work fine.

CH1 VBUS_L
CH2 VSYS_L
CH3 VBAT_L
CH4 ILIM_HIZ_L