current flow OUT 2 ⇒ OUT1
Decay mode: Fast decay

AOUT 1

AOUT 2

motor current

When the current hits the current chopping threshold,
the current flow reverse in a moment.
What is this?