Reset to home state

STEP

ENABLE

nSLEEP

Motor current

From nSLEEP High to STEP
1.5msec

Is there spec of timing from nSLEEP High to ENABLE High?

nSLEEP Low
200usec

Home state