TICSpro issue



When the RESETN is Low(Remove the check button), output frequency stops at all output port. This behavior is normal operation. After that, I think the output frequency restart as setting if we set RESETN is high, however output frequency maintain to be stopped.
So I would like to know the way to avoid this issue.