this is 74.25MHz trace,
this create issue(related to jitter or noise) or not
because it's long trace