REC Operation

Could confirm the expected operation.

HWI	TSK	TSK

USB Int (EP1TX)

mailbox → AC ISO Handler

It seems that if there is not insert the delay on USB_AC task, FIFO will copy the data before reading

If add the delay, this problem did not

Delay

[ASRC]

mailbox

・Copy AC object buffer to EP1 TX FIFO

・Copy ASRC output block to AC object buffer

mailbox → AC ISO Handler

1ms

USB Int (EP1TX)

Could not confirm the expected operation.

HWI	TSK	TSK

USB Int (EP1TX)

mailbox → AC ISO Handler

[ASRC]

mailbox

Write the FIFO before expeding the data

・Copy AC object buffer to EP1 TX FIFO

・Copy ASRC output block to AC object buffer

About 40us

mailbox → AC ISO Handler

USB Int (EP1TX)