

G. Castano

Diagram of the CN4 connector pinout:

- Pin 1: +5V
- Pin 2: D-
- Pin 3: D+
- Pin 4: GND
- Pin 5: GND

