


< USB IN → AC IN >

— Condition : BAT below 3.0V, no-load, ACin=4.8V, USB=5.1V **TS=OFF** —



< USB IN → AC IN >

— Condition: BAT above 3.0V, no-load, ACin=4.8V, USB=5.1V **TS=OFF** —

