Selection of Components for Type II Compensation

The value of R0 is some?




Figure 18. Buck Compensation Components